




# 60TTCS 4" Product Delivery Elbow

## Replacement Parts

Rev. 0, January 2003



ITEM	PART NUMBER	DESCRIPTION	QTY.
1	E00266A	UPPER BODY <sup>4</sup>	1
2	C10056	LOWER BODY	1
3	C10125M	HANDLE <sup>3</sup>	1
4	C10143M	DRIVE STEM (INNER) <sup>3</sup>	1
5	C10144M	DRIVE STEM (OUTER) <sup>3</sup>	1
6	C10145M	ELBOW LINK (UPPER BODY) <sup>3</sup>	1
7	H03114M	HEX CAP SCREW	8
8	H06151M	HEX NUT	8
9	H10039M	GASKET (NEOPRENE FIBER)	1
10	H10090M	FLANGE BEARING	4
11	H04137M	SEAT RING (BUNA)	1
12	H20373M	PIN (CLEVIS) <sup>3</sup>	2
13	H20476M	PIN (SPRING) <sup>2,3</sup>	2
14	H20495M	YOKE ASSEMBLY <sup>2</sup>	2
15	H51427M	SHOULDER SCREW <sup>3</sup>	1
16	H03866M	FLAT WASHER <sup>3</sup>	6
17	H10088M	SPRING WASHER <sup>3</sup>	4
18	H51787M	COTTER PIN <sup>3</sup>	2

ITEM	PART NUMBER	DESCRIPTION	QTY.
19	H04135M	RETAINING PLATE <sup>1,4</sup>	3
20	H52471M	SCREW <sup>1,4</sup>	9
21	H20010M	GASKET (BUNA) <sup>1,4</sup>	3
22	H20583M	WINDOW <sup>1,4</sup>	3
23	C10007M	TUBE	1
24	C10049M	VAPOR ADAPTOR	1
25	H05471M	LIP SEAL (VITON)	1
26	H20191M	O-RING (BUNA)	1
27	H10262M	GASKET (BUNA)	1

REPAIR KITS		
PART NUMBER	DESCRIPTION	QTY.
E00266	UPPER BODY ASSY (W / WINDOWS)	N/A
60WRK	WINDOW REPLACEMENT KIT	N/A
60TTK	YOKE ASSEMBLY REPLACEMENT KIT	N/A
60CSRK	HANDLE/LINKAGE REPLACEMENT KIT	N/A

1 - Included in 60WRK, 2 - Included in 60TTK, 3 - Included in 60CSRK, 4 - Included in E00266